



# SERVICE BULLETIN



SERVICE DEPARTMENT...CHRYSLER-PLYMOUTH DIVISION  
CHRYSLER MOTORS CORPORATION

TECHNICAL INFORMATION ON ☐ IMPERIAL ☐ CHRYSLER ☒ PLYMOUTH ☒ VALIANT

Please refer to Chrysler-Plymouth Service Bulletin No. 63-10 and No. 62-94.

To provide proper sealing of the spark plug tube to the cylinder head and prevent valve train return oil from leaking past the rubber seal, it is recommended that the Tube Seals, Part No. 1947708 be replaced each time the spark plugs are removed.

Part number listed in this bulletin is stock class code "P".

POLICY: INFORMATION ONLY.

J. W. FARLEY  
Manager-Service  
CHRYSLER-PLYMOUTH DIVISION

Nov. 16, 1962

No. 63-18

## ELECTRICAL

SPARK PLUG  
TUBE  
RUBBER SEAL

1960,  
1961,  
1962  
and  
1963  
PLYMOUTH  
AND  
VALIANT  
SIX-CYLINDER  
ENGINES

P-4595-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	