



SERVICE BULLETIN



SERVICE DEPARTMENT... CHRYSLER-PLYMOUTH DIVISION
CHRYSLER MOTORS CORPORATION

TECHNICAL INFORMATION ON ☒ IMPERIAL ☒ CHRYSLER ☐ PLYMOUTH ☒ VALIANT

This bulletin modifies and supersedes Operation Number 2-740 in the 1962 Chrysler and Imperial and Valiant Service Operation Time Schedule.

The time allowance for "Operation 2-740 Tie Rod Ends - Replace" (Two) (Opposite Sides) is in error in the 1962 Chrysler and Imperial and Valiant Service Operation Time Schedule, and should read as follows:

<u>Operation Number</u>	<u>Operation</u>	<u>Time</u>
2-740	Tie Rod Ends - Replace (Two) (Opposite Sides)	.9 hour.

Please correct your 1962 Chrysler and Imperial and Valiant Operation Time Schedule accordingly.

J. W. Farley
J. W. FARLEY
Manager-Service
CHRYSLER-PLYMOUTH DIVISION

October 17, 1962

No. 63-11

MISCELLANEOUS

SERVICE
OPERATION
TIME
SCHEDULE

1962
CHRYSLER
AND
IMPERIAL
AND
VALIANT
MODELS

P-4126-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	