



# SERVICE BULLETIN



SERVICE DEPARTMENT... CHRYSLER-PLYMOUTH DIVISION  
CHRYSLER MOTORS CORPORATION

TECHNICAL INFORMATION ON ☐ IMPERIAL ☐ CHRYSLER ☒ PLYMOUTH ☒ VALIANT

October 17, 1962

No. 63-12

The Operation Number 8-370 in the 1963 Plymouth Service Operation Time Schedule, and Operation Number 2-740 in the 1963 Valiant Service Operation Time Schedule are in error, and should be corrected as shown below:

## PLYMOUTH

Operation Number 8-370 should read:

<u>Operation Number</u>	<u>Operation</u>	<u>Time</u>
8-370	Backup Light Switch - Replace	1.0 hour

## VALIANT

Operation Number 2-740 should read:

<u>Operation Number</u>	<u>Operation</u>	<u>Time</u>
2-740	Tie Rod Ends - Replace (Two) (Opposite Sides)	.9 hour

Please correct your 1963 Plymouth and Valiant Service Operation Time Schedules accordingly.

*J. W. Farley*  
J. W. FARLEY  
Manager-Service  
CHRYSLER-PLYMOUTH DIVISION

## MISCELLANEOUS

### SERVICE OPERATION TIME SCHEDULE

1963  
PLYMOUTH  
AND  
VALIANT  
MODELS

P-4127-C

Service Mgr.	
Shop Foreman	
Technicians	
Parts Mgr.	
Partsmen	